



Plumbing for new style drive motor P/N 140849

Old style drive motors have a secondary drain system. This is not used on new style motors. If replacing both drive motors, remove and discard items 10, 19, 13 and 20. Cap the T item 16 where hose item 20 was removed.



Left side motor replacement only – discard elbow # 10 and hose # 19 from left drive motor. Cap T on top of right drive motor.



If replacing both drive motors refer to this diagram.

If replacing just one drive motor refer to these diagrams.

Right side motor replacement only – discard T # 13 from top of right drive motor and connect hose # 19 and hose # 20 together.

